


SAMPLE REPORT



Shear Strength vs. Water Content (Fall Cone Test)



Site X Remediation

Client: Environmental Engineering Company
Project No.: 12345678
Sample ID: TP01
Depth: 0.5 - 1.5 m

Tested by:

RA

Date Tested:

26-Oct-05

Approved by: